

Powerlink Release Notes Ver. 3.12

Version 3.12 (build 1245):

Date: 27/8-2018

New features:

- 8 cyclic R/W registers possible.
- Writes to the module command register (general command) is made one-shot, when accessing cyclic.
- If having mode register in both cyclic read and cyclic write, the homing modes (12,13,14,25,26) are made one-shot. Meaning that even though it's transmitted cyclic from the PLC it is not overwritten in the motor.

Bug Fixes:

- Occasional erroneous cyclic readings from MAC050-141 corrected.
-

Version 3.10 (build 339):

Date: 12/7-2012

New features:

- Now same .maf file for both MAC and MIS motors
- PDO like communication with SMC85/MIS34x
- 2Mbit communication with SMC85/MIS34x
=> Which together give comm. speed nearly like MAC400->

bug Fixes:

- Power LED enters known state after re-applying P+.
-

Version 3.00:

Date: 8/12-2011

New features:

- MAC050-141 now fully supported.
(Requires version 9.00 or higher of motor firmware)
-

Version 2.00

Date: 30/8-2011

- Changed to newer Powerlink stack version

- LED's now working correctly
- XDD file now matches 100%

Version 1.84

Date: 31/5-2011

- First official release

Version 1.0

Date:

- First test version
-